

# **PRI Construction Materials Technologies LLC**

6412 Badger Drive Tampa, FL 33610 813.621.5777

https://www.pri-group.com/

# **Laboratory Test Report**

Report for:

Jess Varela

Yoder Metals 76 Alberta Rd. Screven, Ga 31560

**Product Name:** 

Coated Metal Roofing Panel AZ50 grade 80

Galvanized Metal Roofing Panel AZ55 grade 80

Project No.:

2181T0001

Dates Tested:

Jul. 22, 2019

Test Methods:

UL 2218 (2010)

Results Summary:

Compliant: UL 2218 Impact Resistance - Class 4

Purpose:

Determine the impact resistance of the identified product in accordance with UL 2218

(2010) Standard for Impact Resistance of Prepared Roof Covering Materials.

Brava Shake is a composite roofing shingle.

Test Methods:

Testing was conducted in accordance with standard test methods.

Test Method

Title

Year

UL 2218

Standard for Impact Resistance of Prepared Roof Covering Materials.

2010

Sampling:

The following materials were received by PRI.

Product	Source	Date	Sampling
Galvalume Panel	Tampa, FL	Jun. 6, 2019	Yoder Metals
Valspar Weather XL Coated Panel Butyl Rubber Sealant	Tampa, FL	Jun. 6, 2019	Yoder Metals
	Tampa, FL	Jun. 6, 2019	Yoder Metals

Products tested were 36in. wide metal roofing panels with 0.75in. rib eight on 9in. centers with a thickness of 0.0142in. Panels were cut to allow a lap to be incorporated in the test specimen. Proponent-supplied butyl rubber sealant was utilized to seal the lap.

## 218170001

The test results, opinions, or interpretations are based on the material supplied by the client. This report is for the exclusive use of stated client. No reproduction or facsimile in any form can be made without the client's permission. This report shall not be reproduced except in full without the written approval of this laboratory. PRI Construction Materials Technologies LLC assumes no responsibility nor makes a performance or warranty statement for this material or products and processes containing this material in connection with this report.

Yoder Metals UL 2218 for Client Supplied Product(s) Page 2 of 2

#### Results:

Physical Properties	Test Method	Results		
		Depression (in)	Result [Pass/Fail]	Requirement
Hail Impact Resistance [Pass/Fail]  2 specimens; Coated Metal Panel;  3ft x 3ft test deck	UL 2218 Class 4			
Class 4; 2.00±0.01in steel ball ø 1.15±0.04lb steel ball mass	Impact Location #1	0.13	Pass	Report
20.0ft steel ball drop 23.71ft-lb impact kinetic energy 2 drops per impact location 6 impact locations	Impact Location #2	0.50	Pass	
	Impact Location #3	0.25	Pass	
	Impact Location #4	0.50	Pass	
	Impact Location #5	0.75	Pass	
	Impact Location #6	0.75	Pass	
Hail Impact Resistance [Pass/Fail]  2 specimens; Galvanized Metal Panel;  3ft x 3ft test deck	UL 2218 Class 4			The state of the s
Class 4; 2.00±0.01in steel ball ø	Impact Location #1	0.05	Pass	
1.15±0.04lb steel ball mass	Impact Location #2	0.50	Pass	Report
20.0ft steel ball drop 23.71ft-lb impact kinetic energy	Impact Location #3	0.20	Pass	
	Impact Location #4	0.25	Pass	
2 drops per impact location	Impact Location #5	0.50	Pass	
6 impact locations	Impact Location #6	0.75	Pass	

#### Statement of Attestation:

The results of testing were determined in accordance with and UL 2218 (2010) Standard for Impact Resistance of Prepared Roof Covering Materials. The laboratory test results presented in this report are representative of the material supplied.

Brent Barbeau Manager

08/01/2019

#### Report Issue History:

Date

Issue #	Date	Pages	Revision Description (if applicable)
Original	08/1/2019	2	NA

### **END OF REPORT**

The test results, opinions, or interpretations are based on the material supplied by the client. This report is for the exclusive use of stated client. No reproduction or facsimile in any form can be made without the client's permission. This report shall not be reproduced except in full without the written approval of this laboratory. PRI Construction Materials Technologies LLC assumes no responsibility nor makes a performance or warranty statement for this material or products and processes containing this material in connection with this report.